



Environment Care

development and

operation, the Gas

& Protection

During its

Environmental responsibility.



ACCESS ROAD REHABILITATION

In 2022, nearly 2 km of access roads were rehabilitated, benefiting the surrounding communities.



EROSION CONTROL

Erosion control works are being carried out and maintained in the areas surrounding the Gasoducto Morelos right-of-way.



AFFLUENT BANK PROTECTION

GDM monitors and maintains the rockfill works on the banks of the affluents crossed by the project.





